



IECEX CoC Certified Service Facility

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

Certificate No.:	IECEX SIR S0020	Page 1 of 1	<u>Certificate history:</u>
Status:	Current	Issue No: 3	Issue 3 (2022-09-05)
Date of Issue:	2022-09-05		Issue 2 (2021-12-09)
			Issue 1 (2021-06-28)
			Issue 0 (2014-01-03)
Applicant:	Quartzelec Limited - Aberdeen 20 Howe Moss Drive Dyce Aberdeen AB21 0GL United Kingdom		
Type of Service:	Repair and Overhaul according to IEC 60079-19		
Type of Protection:	Dusts to IEC 60079-31 "t", Flameproof Enclosure "d", Increased Safety "e", Type of Protection "n"		
Scope of Service:	repair and overhaul of Ex rotating machines and terminal boxes (Ex d, e, n, t)		

Locations covered by this Certificate:

Quartzelec Limited - Aberdeen
20 Howe Moss Drive
Dyce
Aberdeen AB21 0GL
United Kingdom

Facility Audit Report:

GB/SIR/FAR11.0002/00	GB/SIR/FAR11.0002/01	GB/SIR/FAR11.0002/02
GB/SIR/FAR11.0002/03	GB/SIR/FAR11.0002/04	GB/SIR/FAR11.0002/05
GB/SIR/FAR11.0002/06	GB/SIR/FAR11.0002/07	GB/SIR/FAR11.0002/08
GB/SIR/FAR11.0002/09	GB/SIR/FAR11.0002/10	GB/SIR/FAR11.0002/11

This certificate is issued as verification that the Service Facility and associated locations were assessed and found to comply with the IECEx Scheme requirements, relating to the type and scope of service listed above. This certificate is granted subject to the conditions as set out in IECEx Scheme Rules, IECEx 03 and Operational Documents as amended.

Approved for issue on behalf of the IECEx
Certification Body:

Matthew Fielding

Position:

Audits Team Manager

Signature:
(for printed version)

Date:
(for printed version)

1. This certificate and schedule may only be reproduced in full.
2. This certificate is not transferable and remains the property of the issuing body.
3. The Status and authenticity of this certificate may be verified by visiting www.iecex.com or use of this QR Code.



Certificate issued by:

CSA Group Testing UK Ltd
Unit 6, Hawarden Industrial Park
Hawarden, Deeside CH5 3US
United Kingdom

sira
CERTIFICATION





IECEX CoC Certified Service Facility

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEX Scheme visit www.iecex.com

Certificate No.: **IECEX EXV S0004** Page 1 of 1 [Certificate history:](#)
Issue 0 (2022-02-09)

Status: **Current** Issue No: 0

Date of Issue: 2022-02-09

Applicant: **Quartzelec Middle East**
TWH-20 ADNOC L&S Complex
Mussafah
Abu Dhabi P.O. Box 109891
United Arab Emirates

Type of Service: **Repair and Overhaul according to IEC 60079-19**

Type of Protection: **Flameproof Enclosure "d", Increased Safety "e", Type of Protection "n"**

Scope of Service: Overhaul and rewinding of Ex motors

Locations covered by this Certificate:

Quartzelec Middle East
TWH-20 ADNOC L&S Complex
Mussafah
Abu Dhabi P.O. Box 109891
United Arab Emirates

Facility Audit Report:

[GB/EXV/FAR22.0001/00](#)

This certificate is issued as verification that the Service Facility and associated locations were assessed and found to comply with the IECEX Scheme requirements, relating to the type and scope of service listed above. This certificate is granted subject to the conditions as set out in IECEX Scheme Rules, IECEX 03 and Operational Documents as amended.

Approved for issue on behalf of the IECEX
Certification Body:

Craig Nutty

Position:

Quality Manager / Principal Auditor

Signature:
(for printed version)

Date:

1. This certificate and schedule may only be reproduced in full.
2. This certificate is not transferable and remains the property of the issuing body.
3. The Status and authenticity of this certificate may be verified by visiting www.iecex.com or use of this QR Code.



Certificate issued by:

ExVeritas Limited
Units 16-18 Abenbury Way
Wrexham Ind. Est.
Wrexham LL139UZ
United Kingdom





IECEX CoC Certified Service Facility

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEX Scheme visit www.iecex.com

Certificate No.: **IECEX SIR S0019** Page 1 of 1 [Certificate history:](#)
Status: **Current** Issue No: 1 [Issue 1 \(2021-04-15\)](#)
[Issue 0 \(2014-01-03\)](#)
Date of Issue: 2021-04-15
Applicant: **Quartzelec Limited**
Armstrong Street
Grimsby DN31 1XD
United Kingdom
Type of Service: **Repair and Overhaul according to IEC 60079-19**
Type of Protection: **Dusts to IEC 60079-31 "t", Flameproof Enclosure "d", Increased Safety "e", Type of Protection "n"**
Scope of Service: repair and overhaul of Ex rotating machines and terminal boxes (Ex d, e, n, t)

Locations covered by this Certificate:

Quartzelec Limited
Armstrong Street
Grimsby DN31 1XD
United Kingdom

Facility Audit Report:

[GB/SIR/FAR12.0001/00](#)
[GB/SIR/FAR12.0001/04](#)
[GB/SIR/FAR12.0001/07](#)

[GB/SIR/FAR12.0001/02](#)
[GB/SIR/FAR12.0001/05](#)

[GB/SIR/FAR12.0001/03](#)
[GB/SIR/FAR12.0001/06](#)

This certificate is issued as verification that the Service Facility and associated locations were assessed and found to comply with the IECEX Scheme requirements, relating to the type and scope of service listed above. This certificate is granted subject to the conditions as set out in IECEX Scheme Rules, IECEX 03 and Operational Documents as amended.

Approved for issue on behalf of the IECEX
Certification Body:

Matthew Fielding

Position:

Audits Team Manager

Signature:
(for printed version)

Date:

1. This certificate and schedule may only be reproduced in full.
2. This certificate is not transferable and remains the property of the issuing body.
3. The Status and authenticity of this certificate may be verified by visiting www.iecex.com or use of this QR Code.



Certificate issued by:

CSA Group Testing UK Ltd
Unit 6, Hawarden Industrial Park
Hawarden, Deeside CH5 3US
United Kingdom





IECEX CoC Certified Service Facility

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

Certificate No.: **IECEX SRM S0004** Page 1 of 1 **Certificate history:**
Status: **Current** Issue No: 4 **Issue 4 (2021-01-22)**
Date of Issue: 2021-01-22 **Issue 3 (2018-05-18)**
Issue 2 (2017-07-13)
Issue 1 (2016-11-01)
Issue 0 (2015-06-01)
Applicant: **QUARTZELEC SDN. BHD.**
Lot 55631, Jalan Sellathevan
Seksyen 36, Shah Alam
Selangor Darul Ehsan 40450
Malaysia
Type of Service: **Repair and Overhaul according to IEC 60079-19**
Type of Protection: **Flameproof Enclosure "d", Increased Safety "e", Type of Protection "n"**
Scope of Service: **Repair and Overhaul of Rotating Machines and Enclosure. (Flameproof Enclosure Ex d, Increased Safety Ex e and Type of Protection Ex n)**

Locations covered by this Certificate:

QUARTZELEC SDN. BHD.
Lot 55631, Jalan Sellathevan
Seksyen 36, Shah Alam
Selangor Darul Ehsan 40450
Malaysia

Facility Audit Report:

[MY/SRM/FAR15.0002/00](#)
[MY/SRM/FAR15.0002/03](#)

[MY/SRM/FAR15.0002/01](#)

[MY/SRM/FAR15.0002/02](#)

This certificate is issued as verification that the Service Facility and associated locations were assessed and found to comply with the IECEx Scheme requirements, relating to the type and scope of service listed above. This certificate is granted subject to the conditions as set out in IECEx Scheme Rules, IECEx 03 and Operational Documents as amended.

Approved for issue on behalf of the IECEx
Certification Body:

Muhammad Nazif Zakaria

Position:

Deputy Certification Manager

Signature:
(for printed version)

Date:

2021-01-22

1. This certificate and schedule may only be reproduced in full.
2. This certificate is not transferable and remains the property of the issuing body.
3. The Status and authenticity of this certificate may be verified by visiting www.iecex.com or use of this QR Code.



Certificate issued by:

SIRIM QAS International Sdn Bhd
Building 8, SIRIM Complex, No. 1, Persiaran Dato Menteri
Section 2, PO Box 7035, 40700 Shah Alam
Selangor Darul Ehsan
Malaysia





IECEX CoC Certified Service Facility

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

Certificate No.: **IECEX SIR S0018** Page 1 of 1 Certificate history:
Status: **Current** Issue No: 2 [Issue 2 \(2021-12-17\)](#)
Date of Issue: 2021-12-17 [Issue 1 \(2021-04-15\)](#)
[Issue 0 \(2014-01-03\)](#)
Applicant: **Quartzelec Limited**
Caxton Way
Dinnington
Sheffield
S25 3QE
United Kingdom
Type of Service: **Repair and Overhaul according to IEC 60079-19**
Type of Protection: **Dusts to IEC 60079-31 "t", Flameproof Enclosure "d", Increased Safety "e", Type of Protection "n"**
Scope of Service: repair and overhaul of Ex rotating machines and terminal boxes (Ex d, e, n, t)

Locations covered by this Certificate:

Quartzelec - Sheffield

Caxton Way
Dinnington
Sheffield
S25 3QE

Facility Audit Report:

GB/SIR/FAR12.0002/00
GB/SIR/FAR12.0002/03
GB/SIR/FAR12.0002/06

GB/SIR/FAR12.0002/01
GB/SIR/FAR12.0002/04
GB/SIR/FAR12.0002/07

GB/SIR/FAR12.0002/02
GB/SIR/FAR12.0002/05

This certificate is issued as verification that the Service Facility and associated locations were assessed and found to comply with the IECEx Scheme requirements, relating to the type and scope of service listed above. This certificate is granted subject to the conditions as set out in IECEx Scheme Rules, IECEx 03 and Operational Documents as amended.

Approved for issue on behalf of the IECEx
Certification Body:

Matthew Fielding

Position:

Audits Team Manager

Signature:
(for printed version)

Date:

1. This certificate and schedule may only be reproduced in full.
2. This certificate is not transferable and remains the property of the issuing body.
3. The Status and authenticity of this certificate may be verified by visiting www.iecex.com or use of this QR Code.



Certificate issued by:

CSA Group Testing UK Ltd
Unit 6, Hawarden Industrial Park
Hawarden, Deeside CH5 3US
United Kingdom





IECEX CoC Certified Service Facility

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEX Scheme visit www.iecex.com

Certificate No.:	IECEX SIR S0010	Page 1 of 1	<u>Certificate history:</u>
Status:	Current	Issue No: 4	Issue 4 (2021-12-07)
Date of Issue:	2021-12-07		Issue 3 (2021-04-15)
Applicant:	Quartzelec Limited Quartzelec - Swansea Felinfach Swansea West Business Park Swansea SA5 4HF United Kingdom		Issue 2 (2013-12-23)
Type of Service:	Repair and Overhaul according to IEC 60079-19		Issue 1 (2012-06-08)
Type of Protection:	Dusts to IEC 60079-31 "t", Flameproof Enclosure "d", Increased Safety "e", Type of Protection "n"		Issue 0 (2011-05-06)
Scope of Service:	repair and overhaul of Ex rotating machines and terminal boxes (Ex d, e, n, t)		

Locations covered by this Certificate:

Quartzelec Limited
Quartzelec - Swansea
Felinfach
Swansea West Business Park
Swansea SA5 4HF
United Kingdom

Facility Audit Report:

[GB/SIR/FAR11.0001/00](#)
[GB/SIR/FAR11.0001/03](#)
[GB/SIR/FAR11.0001/06](#)
[GB/SIR/FAR11.0001/09](#)

[GB/SIR/FAR11.0001/01](#)
[GB/SIR/FAR11.0001/04](#)
[GB/SIR/FAR11.0001/07](#)

[GB/SIR/FAR11.0001/02](#)
[GB/SIR/FAR11.0001/05](#)
[GB/SIR/FAR11.0001/08](#)

This certificate is issued as verification that the Service Facility and associated locations were assessed and found to comply with the IECEX Scheme requirements, relating to the type and scope of service listed above. This certificate is granted subject to the conditions as set out in IECEX Scheme Rules, IECEX 03 and Operational Documents as amended.

Approved for issue on behalf of the IECEX
Certification Body:

Matthew Fielding

Position:

Audits Team Manager

Signature:
(for printed version)

Date:

1. This certificate and schedule may only be reproduced in full.
2. This certificate is not transferable and remains the property of the issuing body.
3. The Status and authenticity of this certificate may be verified by visiting www.iecex.com or use of this QR Code.



Certificate issued by:

CSA Group Testing UK Ltd
Unit 6, Hawarden Industrial Park
Hawarden, Deeside CH5 3US
United Kingdom





IECEX CoC Certified Service Facility

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEX Scheme visit www.iecex.com

Certificate No.: **IECEX CSAE S0002** Page 1 of 1 Certificate history:
Status: **Current** Issue No: 0 Issue 0 (2021-08-19)
Date of Issue: 2021-08-19
Applicant: **Quartzelec Limited**
Castle Mound Way
Central Park
Rugby
Warwickshire
CV23 0WB
United Kingdom
Type of Service: **Repair and Overhaul according to IEC 60079-19**
Type of Protection: **Dusts to IEC 60079-31 "t", Flameproof Enclosure "d", Increased Safety "e", Type of Protection "n"**
Scope of Service: repair and overhaul of Ex rotating machines and terminal boxes (Ex d, e, n, t)

Locations covered by this Certificate:

Quartzelec Limited
Castle Mound Way
Central Park
Rugby
Warwickshire
CV23 0WB
United Kingdom

Facility Audit Report:

GB/CSAE/FAR21.0002/00

This certificate is issued as verification that the Service Facility and associated locations were assessed and found to comply with the IECEX Scheme requirements, relating to the type and scope of service listed above. This certificate is granted subject to the conditions as set out in IECEX Scheme Rules, IECEX 03 and Operational Documents as amended.

Approved for issue on behalf of the IECEX
Certification Body:

Matthew Fielding

Position:

Audits Team Manager

Signature:
(for printed version)

Date:
(for printed version)

1. This certificate and schedule may only be reproduced in full.
2. This certificate is not transferable and remains the property of the issuing body.
3. The Status and authenticity of this certificate may be verified by visiting www.iecex.com or use of this QR Code.



Certificate issued by:

CSA Group Testing UK Ltd
Unit 6, Hawarden Industrial Park
Hawarden, Deeside CH5 3US
United Kingdom

